
Fig. 1



OEELCE AND A STATE OF THE STATE

DOCKET NO.: 8027-1026 APPLN NO.: 09/764,880 REPLY TO NOTICE OF ALLOWABILITY OF: JANUARY 27, 2005 REPLACEMENT SHEET 2 of 6

Fig. 2A




Fig. 2B





Fig. 2C

SURFACE LEVEL OF
FIRST INSULATING FILM
AFTER IT IS ETCHED

SURFACE LEVEL OF FIRST
INTERLAYER INSULATING FILM AFTER
POLYSILICON IS ETCHED BACK

17
15
12
13





DOCKET NO.: 8027-1026 APPLN NO.: 09/764,880 REPLY TO NOTICE OF ALLOWABILITY OF: JANUARY 27, 2005 REPLACEMENT SHEET 4 of 6






Fig. 5A (PRIOR ART)




Fig. 5B (PRIOR ART)




Fig. 5C (PRIOR ART)






Fig. 6 (PRIOR ART)

